



別図1 委託対象施設全域図





凡例


包括対象

— 本委託対象施設

0 1,250 2,500 5,000
m







南⑧

南③

南⑤





南④


南⑥


南⑦


新堀川




























凡例

— その他路線

2期管渠点検

- 2025(対象路線無)
- 2026(対象路線無)
- 2027
- 2027(腐食)
- 2028
- 2029

第2期管路包括管渠点検箇所位置図

0 500 1,000 2,000
m



凡例


- その他路線
- 2期管渠調査**
- 2029
- 2028
- 2027
- 2027(腐食点検後調査)
- 2026
- 2026(点検後調査)
- 2025
- 2025(点検後調査)

※点検後調査：R5、R6年実施の点検の結果、異状が確認される路線は
想定のため2027年、2028年の点検後調査箇所は未表記

第2期管路包括管渠調査箇所位置図

0 500 1,000 2,000 m

別図5 マンホール内部・蓋点検
マンホール内部・蓋調査




- 凡例**
- 2期MH点検
- 2025(対象施設無)
 - 2026
 - 2027
 - 2027(腐食)
 - 2028
 - 2029


第2期管路包括MH点検箇所位置図


0 500 1,000 2,000
m

別図6(1/6) 汚水桝つまり定期清掃




別図6(2/6) 汚水桝つまり定期清掃






別図6(4/6) 汚水桝つまり定期清掃




別図6(5/6) 汚水桧つまり定期清掃




別図6(6/6) 汚水桝つまり定期清掃



別図7 本管つまり定期清掃(1/4)







別図7 本管つまり定期清掃(4/4)

